# CSI Country Wide Case Study Safety Strategy Discussion

# **Construction Safety Investigator**

## Instructions

# 

The objective of this tool is to provide field supervisors with information to proactively engage workers and discuss safety related concerns that they may encounter. Safety discussions should not be limited to the subject above and should pertain to the activities that workers will be involved in that may have the potential for safety related exposures.

# Case Day:

August 2007

# Accident Type:

Aerial Lift Accident - Boom Collapse

#### Relevant laws, rules and codes may include:

29 CFR 1926.453 and 1926.454, 29CFR 1910.67, ANSI/SIA A92.5-1992 "Boom-supported Elevating Work Platforms", Aerial Lift Manufacturer's Operation and Maintenance Specifications/Instructions

#### Case:

A mechanic sustained fatal injuries and a coworker was injured after the boomsupported aerial work platform they were riding collapsed.

## Accident Detail:

The incident occurred at a college campus where the two workers were installing a sign on the campus Field House. The Field House is approximately 35 feet high and the sign was to be placed on the upper front section of the building. A boom-supported aerial work platform was used to elevate the workers. At the time of the incident, the victim with fatal injuries and the coworker were inside the lift basket. Both workers wore personal fall arrest systems (PFAS). The victim's lanyard was attached to the lift basket. The coworker's lanyard was not attached. At approximately 11:40 a.m., the boom of the work platform suddenly collapsed and the lift basket crashed to the ground. The victim and the coworker fell approximately 40 feet. Campus security was notified immediately and paramedics arrived within minutes. Both workers were transported to a hospital where the victim died an hour later. The coworker suffered serious injuries and survived.

## **Reconstructive Safety Evaluation:**

- What are some of the possible causes of the accident being discussed?
- What actions could have been taken that might have prevented this accident from occurring?

#### Accident Scene Conclusion:

The collapse of the work platform was determined to be caused by the failure of the upright level cylinder: the rod of the cylinder had broken away from the cylinder barrel. The investigation found that the rod assembly of the failed cylinder had been modified and this modification caused the cylinder to fail. The thread of the failed cylinder rod had been ground off and a hole had been drilled through the rod. The hex nut had been drilled through to allow a bolt to be inserted to hold the rod and the nut together. A bolt had been inserted through the hex nut and the rod and had been fastened with a nut. The bolt broke into three pieces during the incident and caused the cylinder to fail.

# **Preventive Safety Measures Include:**

- Prohibit unauthorized modifications of or alterations to the aerial work platform
- Ensure that after purchase of a pre-owned aerial work platform, the machine is thoroughly inspected by a dealer or a qualified mechanic before use
- Ensure that periodic inspections and preventive maintenance are carried out in strict accordance with the manufacturer's specifications
- · Keep and maintain operation and maintenance manuals for aerial work platforms
- Train all maintenance personnel to strictly follow the manufacturer's requirements when performing machine maintenance

#### Attendance Roster

Reference: This case was reported in the NIOSH Fatality Assessment and Control Evaluation (FACE) Program, New York Case Report 07NY080.

# Chubb. Insured.™

Chubb is the marketing name used to refer to subsidiaries of Chubb Limited, providing insurance and related services. For a list of these subsidiaries, please visit our website, www.chubb.com. Insurance is provided by ACE American Insurance Company and its U.S. based Chubb underwriting company affiliates. All products may not be available in all states. This communication contains product summaries only. Coverage is subject to the language of the policies as actually issued. Surplus lines insurance is sold only through licensed surplus lines producers. Loss control evaluations, reports, recommendations and services are made solely to assist the insurer in underwriting and loss control and are not to be construed as an added benefit for the insured, property owner or any other party (this may not apply if loss control services are purchased separately and specifically pursuant to a service agreement). Evaluation for any hazard or condition does not imply that it is covered under any policy. Chubb is the world's largest publicly traded property and casualty insurance group. With operations in 54 countries, Chubb provides commercial and personal property and casualty insurance, personal accident and supplemental health insurance, reinsurance and life insurance to a diverse group of clients. Chubb Limited, the parent company of Chubb, is listed on the New York Stock Exchange (NYSE: CB) and is a component of the S&P 500 index.