CSI Country Wide Case Study Safety Strategy Discussion

Construction Safety Investigator

Instructions

CHUBB

The objective of this tool is to provide field supervisors with information to proactively engage workers and discuss safety related concerns that they may encounter. Safety discussions should not be limited to the subject above and should pertain to the activities that workers will be involved in that may have the potential for safety related exposures.

Case Day: February 2009

Accident Type: Occupational Health Accident - Lead Exposure

Relevant laws, rules and codes may include: 29CFR 1926.20(a)(1), 1926.21(b)(2), (3), 1926.62, 1910.134

Case:

Two workers were hospitalized after being exposed to high concentrations of lead based paint.

Accident Detail:

Two workers employed by a bridge demolition contractor, were involved in removing sections of bridge paint at pre-determined locations in preparation for demolition.

The workers were using needle scalers to remove the bridge paint down to bare metal at locations where either sections of the bridge are cut using torches or hydraulic shears. Needle scalers are pneumatic tools with fine chisels called needles that move against the work surface removing paint or other coatings.

During the scaling process, paint is chipped into fine particles that can be inhaled or ingested. After three days of scaling, both workers became ill and were taken to local area hospitals where they were found to have lead poisoning.

Reconstructive Safety Evaluation:

- What are some of the possible causes of the accident being discussed?
- What actions could have been taken that might have prevented this accident from occurring?

Accident Scene Conclusion:

The investigation revealed that the contractor did have a written lead protection program, however, failed to implement it for this project.

The workers wore only dust masks to protect from inhalation, there were no hygiene facilities to clean up before eating, drinking or leaving for the day, workers reused contaminated coveralls as protective clothing and the workers were not part of a blood lead level monitoring program.

In addition, it was revealed that the workers had worked for this contractor for several months and performed these operations on several occasions, which likely contributed to their over exposures to lead.

Preventive Safety Measures Include:

- All operations are preplanned using a Job Safety Task Analysis (JSTA) to ensure potential safety hazards associated with an operation are identified and appropriate steps are taken to eliminate or control them.
- Where the potential of lead exposure exists, all operations in question are fully evaluated to determine the extent of the exposure. If lead exposures exist, a written lead protection program is created and fully implemented before work begins.
- All workers involved in operations with lead exposures are trained in the hazards of the work they are to perform, the personal protective equipment, hygiene facilities, respiratory protection and safe work procedures necessary to perform their assigned tasks.

Attendance Roster

Reference: This case is fictitious, and any resemblance to any persons, living or dead, is entirely coincidental. However, the type of accident described in this case summary happens all too often on construction sites.

Chubb. Insured.[™]

Chubb is the marketing name used to refer to subsidiaries of Chubb Limited, providing insurance and related services. For a list of these subsidiaries, please visit our website, www.chubb.com. Insurance is provided by ACE American Insurance Company and its U.S. based Chubb underwriting company affiliates. All products may not be available in all states. This communication contains product summaries only. Coverage is subject to the language of the policies as actually issued. Surplus lines insurance is sold only through licensed surplus lines producers. Loss control evaluations, reports, recommendations and services are made solely to assist the insurer in underwriting and loss control and are not to be construed as an added benefit for the insured, property owner or any other party (this may not apply if loss control services are purchased separately and specifically pursuant to a service agreement). Evaluation for any hazard or condition does not imply that it is covered under any policy. Chubb is the world's largest publicly traded property and casualty insurance group. With operations in 54 countries, Chubb provides commercial and personal property and casualty insurance, personal accident and supplemental health insurance, reinsurance and life insurance to a diverse group of clients. Chubb Limited, the parent company of Chubb, is listed on the New York Stock Exchange (NYSE: CB) and is a component of the S&P 500 index.